

**RGU FIRE STATISTICS 1<sup>st</sup> AUGUST 2017 TO 31<sup>st</sup> JULY 2018**

<b>COMPILED BY:</b>	<b>Alan Fleming, Fire Safety Adviser</b>
<b>PHONE:</b>	<b>01224 262082</b>
<b>EMAIL:</b>	<b>a.fleming3@rgu.ac.uk</b>

<b>HALLS OF RESIDENCE FIRES</b>	
Total number of major fires*:	<b>1</b>
Total number of minor fires*:	<b>2</b>
Total number of near miss fire incidents*:	<b>1</b>
Total number cooking fires:	<b>2</b>
Total number of external fires:	<b>0</b>
Number of internal that do not result in fire alarm activations:	<b>0</b>
Summarise briefly the nature of the fire(s)/ incidents below:	
Major fire - dressing gown came in contact with lit candle. Minor fire - cooking fire when oil was spilt on hob. Minor fire - cooking fire due to build-up of crumbs in toaster Near miss – plastic container left on hot hob causing fumes.	

*\*Refer to definition*

<b>FALSE ALARMS</b>	
Number of malicious alarms:	<b>0</b>
Number of other false activations:	<b>65</b>
Total number of fire alarm activations	<b>69</b>

<b>INJURIES FROM FIRE</b>	
Number of injuries as a result of fire:	<b>0</b>
Summarise briefly the nature of the injuries below:	

Total number of Fire & Rescue Services attendance:	<b>3</b>
Number of automatic detectors:	<b>910</b>

<b>ALL OTHER BUILDING FIRES</b>	
Total number of major fires*:	<b>0</b>
Total number of minor fires*:	<b>0</b>
Total number of near miss fire incidents*:	<b>0</b>
Total number of cooking fires:	<b>0</b>
Total number of external fires:	<b>1</b>
Number of internal that do not result in fire alarm activations:	<b>0</b>
Summarise briefly the nature of the fire(s)/ incidents below:	
External fire – fire in bin outside RGU Sport, extinguished by Sport staff member with extinguisher.	

*\*Refer to definition*

<b>FALSE ALARMS</b>	
Number of malicious alarms:	<b>1</b>
Number of other false activations:	<b>12</b>
Total number of fire alarm activations	<b>13</b>

<b>INJURIES FROM FIRE</b>	
Number of injuries as a result of fire:	<b>0</b>
Summarise briefly the nature of the injuries below:	

Total number of Fire & Rescue Services attendance:	<b>7</b>
Number of automatic detectors:	<b>3025</b>